

Below is a diagram of a basic compressed air system configuration that can be followed to help supply adequate flow, as well as, dry filtered air to point of use pneumatic tooling and equipment. Positioning a **Porta-Dry**, portable compressed air drying and filtration system, at a location that is close to your work area but as far away as possible from the compressor is ideal. The Porta-Dry unit will effectively remove bulk water, water vapor, unwanted oil and particulates from your air supply resulting in lower operating costs, a safer work area and an increase in pneumatic tooling and equipment life.

